
SVGA-800S-HDMI Connection

MRA Digital, LLC
www.mradigital.com
info@mradigital.com
443-224-8955
SVGA-800S-HDMI Driver Board
Cable Connection Guide

SVGA-800S-HDMI Cable Connection Guide SVGA OLED Connection

1. The OLED connector is NOT keyed and thus it should be connected to the Driver board as shown in the photo.





HDMI and USB Cable Connections

- 1. Plug the HDMI cable into your PC or your video source.
- 2. The Micro HDMI end of the HDMI cable should be connected as denoted in the photo. Use MicroHDMI-1 input only if applying single video signal.
- 3. Be sure download and install the USB driver for the configuration cable from our website.
- 4. The Micro USB port is used both for configuration purposes and to power the board.


Power Cable Connections

- 1. The SVGA-800S-HDMI Driver can be powered using +5.0v DC
- 2. Connect USB end of the cable to USB PC connector.
- 3. The Micro USB end of the cable should be connected as denoted in the photo
- 4. The USB cable, marked as "CONFIG" can be used with the e-Magin configuration software. (Attention: It does not provide power to Driver and should be used along with Power cable).



- 1. Once the USB driver is installed, a virtual COM port will be installed on your PC. This configuration software uses the virtual COM port to communicate with the SXGA Driver board.
- 2. To find the virtual COM port number go to the Device Manager window and then expand the Port(COM &LPT) option. In the photo shown the virtual COM port number is 4. The COM port number will stay the same as along as you are using the same configuration cable.
- 3. The Virtual COM port number MUST be used when starting up the configuration software or upgrading the firmware within the Driver Board.

Working With the USB Config Cable
Click Here to Download USB Driver



MRA Digital- www.mradigital.com

Power Up Sequence

- 1. There is no particular power up sequence, but a few examples are as follows:
- Ex1. With PC on
- a. Connect HDMI cable to Video Source and to the Driver board
- b. The PC may make a noise which indicates that a new monitor has been connected
- c. This can be verified by going to the monitor properties window
- b. If needed connector USB cable to PC and to the Driver Board
- c. Turn on Power to the Driver Board
- d. An image will be displayed on the OLED
- Fx2. With PC off
- a. Connect HDMI cable to Video Source and to the Driver board
- b. If needed connector USB cable to PC and to the Driver Board
- c. Turn on Power to the Driver Board
- d. Turn on Power to the PC
- e. The LED on the driver board will flash rapidly until a valid video signal is received.
- f. Log into your PC
- g. An image will be displayed on the OLED
- MRA Digital- www.mradigital.com